





Estimado distribuidor:

Rogamos tenga en consideración el comunicado que recibimos de nuestros fabricantes en Asia, advirtiendo de los previsibles problemas de abastecimiento para los próximos 3 meses. Rogamos lo tenga en consideración para sus proyectos en curso.

A new range of shortage of SONY chipset caused by Tailand Flood


1. Our boss just received the news from SONY Senior executives the SONY chipset will become very shortage for the next 3 months. SONY security camera CCD senser, DSP, etc. are made at Tailand factory, and all DSP packaging is done at Tailand. However, the factory has been flooded since Oct. 21th.



2. Many kinds of DSP are made at SONY Tailand Factory, the highest sales quantity 3142 is made from here.



3. You can see that the SONY factory at Tailand was flooded and stoped production, only left the "SONY" logo above the flood. There will be no new chipset from SONY in Nov., and very few chipset can be produced in Dec.
The flood will cause a new range of shortage of SONY chipset at the coming peak period.



4. In Nov., most manufacturters still have stock of chipset for production, as the CCTV industrial was depression during Sept. and Oct. However, the price of SONY chipset have been raised day by day in Mainland China.
So we can predict that it will be a hard period during Dec., because of the shortage of chipset and high prices of cameras.
Hope above information will be useful for your business!